





FIG. 2

FIG.2A













FIG.2G

FIG.2H

UPPER ASSY BRD	TRANSCEIVER SUPPORT SECTION



118

GATEWAY DB9-2 RX

GATEWAY DBP-3 TX

FIG.2I







FIG.3














FIG.3C















FIG.4










FIG.4D




FIG.4E




FIG.4F